

pystykoneen taulukko

| Suoja nro: | Ø A | B | C | Ø D |
|------------|------|-----|-----|------|
| 11 | 109 | 35 | 55 | 190 |
| 14 | 129 | 40 | 60 | 210 |
| 16 | 154 | 45 | 70 | 240 |
| 18 | 173 | 50 | 75 | 260 |
| 20 | 193 | 55 | 90 | 320 |
| 22 | 219 | 60 | 95 | 340 |
| 26 | 259 | 65 | 105 | 380 |
| 32 | 300 | 80 | 130 | 480 |
| 36 | 335 | 90 | 140 | 520 |
| 40 | 382 | 100 | 155 | 560 |
| 45 | 445 | 110 | 170 | 610 |
| 50 | 497 | 130 | 190 | 700 |
| 56 | 557 | 130 | 210 | 760 |
| 63 | 630 | 150 | 230 | 830 |
| 71 | 728 | 170 | 270 | 970 |
| 80 | 825 | 230 | 290 | 1060 |
| 101 | 1040 | 280 | 370 | 1310 |

